
%
1 Color
2 Gobo
3 Gobo Rotation
4 Fix Gobos
5 Pan
6 Tilt
7 Scan speed
8 Prism Rotation
9 Zoom& Focus
10 Strobe
11 Dimming
12 Iris
13 Frost
14 Auto Program
15 Pan High Resolution
16 Tilt High Resolution
100%
75%
50%
25%
0%
GOBO SHAKE
Stop
GOBO INDEXING
GOBO SHAKE
Normal
Blackout by wheels
Blackout by moving
Max
Min
Moving speed
Max
MARCO16
MARCO6
MARCO1
Prism
26°
22°
18°
RANDOM STROBE
Pulse closing slow to fast
Pulse opening fast to slow
Pulse closing slow to fast
Pulse opening fast to slow
Frost
Max
Min
Open
Program 8
Program 7
Program 6
Program 5
Program 4
Program 3
Program 2
Program 1
MOTOR RESET
LAMP SWITCH OFF
LAMP SWITCH ON
Color any position
Normal
16 bit pan move
16 bit tilt move